



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost		SLAS	<b>COUNTY: Durham</b> <b>PERMIT NO.: 32-I</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Meeting:** July 19, 2012 **Date of Last Inspection:** June 27, 2012

**FACILITY NAME AND ADDRESS:**

Currin Brothers, Inc. LCID Landfill No. 2  
 1810 Coley Road  
 Durham, NC 27703

**GPS COORDINATES:** N: 35.97059 E: -78.74094

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Glenn Currin, Co-Owner  
 c. 919-880-6624  
 Allen Currin, Co-Owner  
 c. 919-614-2374  
 Office (Donna Parrish - Secretary): 919-876-1138

**FACILITY CONTACT ADDRESS:**

Currin Brothers, Inc.  
 PO Box 547  
 Fuquay-Varina, NC 27526

**PARTICIPANTS**

John Patrone, NCDENR – Solid Waste Section (SWS)  
 Pat Backus, Environmental Engineer  
 Brian Wootton, Permitting Hydrogeologist  
 Allen Currin, Co-Owner – Currin Brothers, Inc.  
 Glenn Currin, Co-Owner – Currin Brothers, Inc.  
 Stacey Smith, Smith Gardner, Inc.

**STATUS OF PERMIT:**

Permit To Operate (PTO) issued October 21, 2010  
 Permit To Construct (PTC) issued in conjunction with PTO  
 PTO/PTC expiration date October 21, 2015

**PURPOSE OF SITE VISIT:**

Site Meeting

**STATUS OF PAST NOTED VIOLATIONS:**

None

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

On July 19, 2012, John Patrone, Pat Backus, and Brian Wootton met with Allen Currin, Glenn Currin, and Stacey Smith for a site meeting at the Currin Brothers, Inc. LCID Landfill No. 2 on Coley Road in Durham, Durham County.

1. A site meeting, requested by Allen Currin, was conducted at the land clearing and inert debris (LCID) landfill in order that Mr. Currin could explain and refer to current facility operation pertaining to material disposal.
2. The facility will be in discussion with SWS - Permitting Branch.
3. The facility has installed edge of waste markers (green metal stakes with orange ribbons).
4. Allen Currin stated that material is commonly placed in 10 to 12 foot lifts.
5. Glenn Currin stated that the (exposed) side slope of the (soil covered) lift at the working face adjacent to the soil mine/borrow area is ~ 600 to 700 feet in length.

Please contact me if you have any questions or concerns regarding report.



John Patrone  
Environmental Senior Specialist  
***Regional Representative***

Phone: 336-771-5095 Fax: 336-771-4631

Sent on: <u>July 20, 2012</u>		Email		Hand delivery	<b>X</b>	US Mail		Certified No. <u>11</u>
-------------------------------	--	-------	--	---------------	----------	---------	--	-------------------------

Electronic Copies: Jason Watkins, Western District Supervisor  
Jessica Montie, Compliance Officer  
Pat Backus, Environmental Engineer  
Brian Wootton, Permitting Hydrogeologist